800 Independence Ave., S.W. Washington, D.C. 20591

Federal Aviation Administration

Transmittal Letter 16-03

December 18, 2015

PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs,EFFECTIVE UPON PUBLICATION Identified as follows: **AIRAC FDC FDC** STATE CITY AIRPORT **SUBJECT** DATE **NUMBER** DATE RNAV (GPS) RWY 5, 4-Feb-16 WI Marshfield Marshfield Muni 5/0703 12/07/15 Orig-A

AIRAC Date: 4 February 2016

FDC **5/0703** MFI IAP MARSHFIELD MUNI, MARSHFIELD, WI. RNAV (GPS) RWY 5, ORIG-A... DELETE NOTE: HELICOPTER VISIBILITY BELOW 1 SM NA. DELETE NOTE: RWY 5 STRAIGHT-IN AND CIRCLING MINIMUMS NA AT NIGHT..

THIS IS **RNAV (GPS) RWY 5 ORIG-B.** 1512021918-PERM